









121	_			~124	~126	~128	130	J132	J34
	<u>, </u>	OUTPUTS	MOTOR SS_CONTROL	OFF -	OFF -	OFF -	OFF _	OFF -	- NO
	b .	0	, MOTOR	0N	OFF	0FF	0FF	OFF	NO
	$d \longrightarrow e$ $LN-25$ $TRUTH TABLE$		TRIGGER ON	X	X	X	X	F	I
	STRUT	_	OVER TEMP	X	X	X	I	F	F
	d.	INPUTS	OVER CUR 2	X	X	I	F	F	F
	? (·	_	OVER CUR 1	X	I	F	F	F	F
	a - b		MOTOR FEED	I	F	F	F	F	F

F1G.5